



Technical Bulletin- Replacing Heat Exchanger Auto air vent for Plug

Eco King has decided to remove the nuance auto air vent at the top of teh heat exchanger. This was due to possible leaking over. With the manual air vent on the heat exchanger this part became redundant. Please see attached picture for the new **EK HXPLG**

EK HXPLG



EK HXPLG Installed



For questions or clarification, please contact King Heating Products;

King Heating Technical

Western Canada-604-385-3265

Eastern Canada-905-334-0651